

# Oil Field Environmental Incident Summary

**Incident:** 20160724153550

**Date/Time of Notice:** 07/24/2016 15:35

**Responsible Party:** MUREX PETROLEUM CORPORATION

**Well Operator:** MUREX PETROLEUM CORPORATION

**Well Name:** HOIBY 4-31 SWD

**Field Name:** BATTLEVIEW

**Well File #:** 8464

**Date Incident:** 7/22/2016

**Time Incident:** 12:30

**Facility ID Number:**

**County:** BURKE

**Twp:** 159

**Rng:** 94

**Sec:** 31

**Qtr:** NW NW

**Location Description:**

**Submitted By:** William Jansky

**Received By:**

**Contact Person:** Shannon Holter  
363 N. Sam Houston Pkwy. E.  
Suite 200  
HOUSTON, TX 77060

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	15	Barrels	13	Barrels		
<b>Brine</b>	5	Barrels	3	Barrels		

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

***Potential Environmental Impacts:***

None

***Action Taken or Planned:***

The source well pump was shut down to stop the flow. Vacuum truck was called to remove fluids. Impacted material will be removed.

***Wastes Disposal Location:*** Fluids to production tank. Solids TBD.

***Agencies Involved:***

***Updates***

---

***Date:*** 7/25/2016    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** O'Gorman, Brian

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a tank overflow, remained within facility diking according to the report. NDIC retains oversight.